

BUREAU VERITAS FACTORY ASSESSMENT REPORT (LEGO SYSTEM A/S)

BUREAU VERITAS PROPRIETARY - copyright Bureau Veritas [2004] DO NOT DISCLOSE OUTSIDE YOUR ORGANISATION WITHOUT BUREAU VERITAS PRIOR WRITTEN CONSENT

Audit Results						
Total Compliance	Non Conformance(s)				Fellow up	
Total Compliance Level to Standard	Critical(s)	Major(s)	Minor(s)	Risk Level for Supply	Follow-up frequency	
88.12%	0	1	22	ORANGE	NOT APPLICABLE	

Audit Details			
BV Ref:	10193470987		
Auditor:	JULIAN YAO		
Audit Date:	JUL 13, 2020 - JUL 14, 2020		
Partner Name:	RDP ASIA (SHENZHEN) LIMITED		
Manufacturer Name:	Jia Ying (Hui Zhou) Umbrella Co., Ltd		
Country:	CHINA		

Scope of Audit

AGAINST LEGO_TIER1_HL & TOYS_FA_V01_01JAN2020

The above reflects our findings for the particular factory in concern on the date of our service only. This report does not certify, confirm or imply: a) compliance with any government, industry or association regulations or standards, unless stated otherwise; or, b) the quality of any specific products manufactured by the factory/sellers/suppliers; or, c) the shipment of any specific products. This report does not discharge or release the factory/sellers/suppliers from their commercial, legal or contractual obligations with buyers in respect of products manufactured by the factory/sellers/suppliers. Our services, including reports and certificates, are subject to the General Conditions of Service of Bureau Veritas which have been sent to your company. They can be resent upon written reports contain liability limitation provisions. BV Office Name: Bureau Veritas Shenzhen Company Limited Address:3F, Block A, Min Li Da Industrial Bldg.,4th Area, Hong Hua Ling Industrial Area, Xili, Nanshan District, Shenzhen City, Guanardong Province, Country Name: China

Guangdong Province. Country Name: China



LEGO_TIER1_HL & TOYS_FA_V01_01JAN2020

(LEGO SYSTEM A/S)

BUREAU VERITAS PROPRIETARY - copyright Bureau Veritas [2004] DO NOT DISCLOSE OUTSIDE YOUR ORGANISATION WITHOUT BUREAU VERITAS PRIOR WRITTEN CONSENT.

Performance Overview				
	Audit Deta	ails		
BV Ref:	10193470987			
Auditor:	JULIAN YAO			
Audit Date:	JUL 13, 2020 - JUL 14, 2020			
Date of Previous Audit:	Jan 10, 2019			
Previous Audit #:	10183430115	10183430115		
Vendor Name:	RDP ASIA (SHENZHEN) LIM	RDP ASIA (SHENZHEN) LIMITED		
Factory Name:	Jia Ying (Hui Zhou) Umbrella C	Jia Ying (Hui Zhou) Umbrella Co., Ltd		
Address:	DA HE GANG XINXU TOWN	DA HE GANG XINXU TOWN HUIYANG		
E-Mail Address:	PATRICK@SINOBEST.COM	НК		
Tel:	86-752-3332932	Fax: 86-752-3332290		
Country:	CHINA			
Scope of Audit				
AGAINST LEGO_TIER1_HL & TOYS_FA_V01_01JAN2020				
	Audit Category			

Umbrella

Key Personnel					
		Present at Audit (please tick 'X' below)			
Name	Job Title	Opening Meeting	On-site Audit	Documentation Review	Closing Meeting
Mr. Hou Wencai	Plant Manager	х	х	x	х
Mr. Yu Zhenming	Quality manager	x	х	x	х
Mr. Tan Yufeng	Engineering Supervisor	х		х	Х
Ms. He Xiaona	Production Supervisor	x	x	x	x

Audit Results						
Total Compliance	I	Risk Level for	Follow-up			
Level to Standard	Critical(s)	Major(s)	Minor(s)	Supply	frequency	
88.12%	0	1	22	ORANGE	NOT APPLICABLE	

The above reflects our findings for the particular factory in concern on the date of our service only. This report does not certify, confirm or imply: a) compliance with any government, industry or association regulations or standards, unless stated otherwise; or, b) the quality of any specific products manufactured by the factory/sellers/suppliers; or, c the shipment of any specific products. This report does not discharge or release the factory/sellers/suppliers from their commercial, legal or contractual obligations with buyers in respect of products manufactured by the factory/sellers/suppliers. Our services, including reports and certificates, are subject to the General Conditions of Service of Bureau Veritas which have been sent to your company. They can be resent upon written request. This report cannot be partially copied. Any reader other that the party for which this report has been specifically issued is hereby informed that the General Conditions of Service of Bureau Veritas Contain liability limitation provisions. BV Office Name: Bureau Veritas Shenzhen Company Limited Address:3F, Block A, Min Li Da Industrial Bidg.,4th Area, Hong Hua Ling Industrial Area, Xili, Nanshan District, Shenzhen City, Guangdong Province. Country Name: China

Company Profile

~Factory established: December 21, 2012 (shown on business license)

~Main manufacturing processes: Cutting, Sewing, Assembly(hand stitching) and packing, silk-screen printing process was subcontracted (subcontractor name: Huizhou Huaying Printing Co., Ltd, Address: Xinxu Town, Huiyang District, Huizhou City, Guangdong Province, China).

~Product Category: Umbrella

~Factory area: 5,000 square meters

~Employee number: 31 employees

~Production capacity: About 60,000 pieces per month, and lead time was about 45 ~ 60 days.

~International certification: Nil

~Peak season: Not obviously.

~Major market: United States(40%), Europe(40%), Asia(20%)

~Major customer: GAP, A.S Watson's, etc.

~Product liability insurance and product recall insurance were not purchased.

~Working days: 6 days per week, Monday to Saturday, Saturday was as overtime.

~Working shift: 1 shift (08:00-12:00, 13:30-17:30)



Analysis of Site Compliance

The above reflects our findings for the particular factory in concern on the date of our service only. This report does not certify, confirm or imply: a) compliance with any government, industry or association regulations or standards, unless stated otherwise; or, b) the quality of any specific products manufactured by the factory/sellers/suppliers; or, c the shipment of any specific products. This report does not discharge or release the factory/sellers/suppliers from their commercial, legal or contractual obligations with buyers in respect of products manufactured by the factory/sellers/suppliers. Our services, including reports and certificates, are subject to the General Conditions of Service of Bureau Veritas which have been sent to your company. They can be resent upon written request. This report cannot be partially copied. Any reader other that the party for which this report has been specifically issued is hereby informed that the General Conditions of Service of Bureau Veritas contain liability limitation provisions. BV Office Name: Bureau Veritas Shenzhen Company Limited Address:3F, Block A, Min Li Da Industrial Bidg.,4th Area, Hong Hua Ling Industrial Area, Xili, Nanshan District, Shenzhen City, Guangdong Province. Country Name: China

Page 3 of 7

Degree of compliance Overview (per section)

Section	Green	Yellow	Orange	Red	N/A	Total Questions
1. General Management Elements	13 (68.42%)	6 (31.58%)	0 (0.00%)	0 (0.00%)	0 (0.00%)	19
2. Senior Man/Agement Commitment And Continual Improvement	2 (66.67%)	1 (33.33%)	0 (0.00%)	0 (0.00%)	0 (0.00%)	3
3. Man/Agement System	21 (80.77%)	5 (19.23%)	0 (0.00%)	0 (0.00%)	0 (0.00%)	26
4. Product Control	13 (76.47%)	4 (23.53%)	0 (0.00%)	0 (0.00%)	0 (0.00%)	17
5. Product Conformity Assessment	8 (88.89%)	0 (0.00%)	0 (0.00%)	0 (0.00%)	1 (11.11%)	9
6. Process Control	5 (100.00%)	0 (0.00%)	0 (0.00%)	0 (0.00%)	0 (0.00%)	5
7. Personnel	3 (50.00%)	1 (16.67%)	1 (16.67%)	0 (0.00%)	1 (16.67%)	6
8. Process Management	6 (60.00%)	3 (30.00%)	0 (0.00%)	0 (0.00%)	1 (10.00%)	10
9. Toys Specific	28 (29.17%)	2 (2.08%)	0 (0.00%)	0 (0.00%)	66 (68.75%)	96
OVERALL	99 (51.83%)	22 (11.52%)	1 (0.52%)	0 (0.00%)	69	191 (100%)

Audit Findings Summary					
Critical Non-conformance Section					
Clause Clause Requirement Levels of Non- Audit Findings No. Conformance					
-	Critical	Critical Non-conformance Secti Clause Requirement Levels of Non-			

Please submit a corrective action plan within 14 days after the audit for the nonconformance's mentioned in the above and underneath sections.

	Audit Findings Summary					
Clause No.	Clause Requirement	Levels of Non- Conformance	Audit Findings			
1	General Management Elements					
1.1.1	Building exterior and interior shall be maintained in good conditions to prevent product contamination.		Per manufacturer tour, most building exteriors and interiors were maintained in good condition, but the wall was peeling off was found in sewing workshop.			
1.3.1	Premises are sufficiently illuminated in order to permit effective cleaning, production, monitoring, and inspection.	Minor (YELLOW)	The lighting was adequate in several sampled areas, such as 1,770 lux in IQC inspection area, 839 lux in sewing area, 1,447 lux in IPQC inspection station of sewing workshop, etc., however, the lighting was not adequate in some other areas, such as only 68 lux in incoming materials warehouse, 231 lux in packing area, 223 lux in final QC inspection area, 41 lux in finished products warehouse. For reference, lighting audit requirement should be 150 lux at least in warehouse, 550 lux at least in production area and 750 lux at least in inspection area.			
1.4.1	Cleaning practices shall be completed so as to minimize risk of contamination.	Minor (YELLOW)	The manufacturer established cleaning procedure and kept relevant cleaning records, most working areas were kept clean during this audit, but several tapes were found in the working tables of packing areas.			
1.4.2	All cleaning equipment in all areas are located such that contamination of process, storage, packing, and flow areas is prevented.	Minor (YELLOW)	The manufacturer had designated cleaning equipment storage area, most cleaning equipment were properly stored, but two cleaning equipment were placed closely with incoming materials in incoming materials warehouse but not placed into the designated areas.			
1.5.1	The company shall either contract the services of a competent pest control organization, or shall have trained personnel, for the regular inspection and treatment of premises to deter and eradicate infestation. Where the services of a pest control contractor are employed, the service contract shall be clearly defined and reflect the activities of the site.	(YELLOW)	The manufacturer had established pest control procedure, pest killing records were available, however, it was found that the used chemicals for pest control were not indicated on pest killing records.			
1.5.3	Pest activity report with corrective actions shall be completed and satisfactorily verified.	Minor (YELLOW)	No pest activity report with corrective actions were available in the factory and no evidence was available to prove that the manufacturer conducted pest activity analysis.			
2	SENIOR MAN/AGEMENT COMMITMENT AND CONTINUAL IMPROVEMENT					
2.3	"Quality Improvement Process is in-place. Daily quality review meetings with action plans developed and implemented. Representatives of Production, Equipment AND Machinery Maintenance, and Operator Training departments regularly attend the meetings."	(TELLOW)	The manufacturer did not establish daily quality improvement process, no daily quality review meeting record was available to show that quality department, production department, equipment& machinery maintenance department etc. were attended to discuss and solve the quality issue for quality improvement. For reference, the manufacturer would conduct quality meeting attended by each department once per month, but not all the meeting records were kept.			

3	MAN/AGEMENT SYSTEM		
3.2.2	The policy shall be communicated throughout the company, and regularly reviewed.	Minor (YELLOW)	The manufacturer established quality policy, it was posted in sewing workshop, but based on interview, 2 of 5 selected employees did not know the quality policy.
3.3.1	The company shall define and communicate the levels of responsibility and accountability for staff involved with product safety, legality, and quality.	Minor (YELLOW)	The manufacturer established the job descriptions which include the levels of responsibility and accountability for staff involved with product safety legality and quality, but no records were available to prove that the job descriptions were communicated to relevant employees, based on interview, the employee knew her job description.
3.3.2	There shall be appropriate arrangements in place, to cover for the absence of key staff.	Minor (YELLOW)	The manufacturer established procedure on the arrangement for back-ups of some key staffs, but no updated back-up name list showed name of key staff's back-up persons. From interview of QC inspectors, the quality supervisor would act for her responsibility during her absence.
3.8.2	Raw materials (including packaging), work in progress and finished products shall be identified to ensure traceability.		The manufacturer established product identification and traceability control procedure, per manufacturer tour, most sampled materials, semi-finished products and finished products were properly identified, but a few part of surplus fabric materials in incoming materials warehouse were not identified with lot number, incoming date, etc. to ensure traceability.
3.11.2	All documents in use are the correct version.	Minor (YELLOW)	The manufacturer established document control procedure, most documents were controlled with version number and used in correct order, but the sample list was not controlled with version number.
4	PRODUCT CONTROL		
4.2.4	All chemicals are segregated during storage and separated from raw materials and finished products by a physical barrier.		The manufacturer established chemical materials control procedure, all of them were properly segregated from materials/products, but one chemical container was not identified in the packing workshop.
4.3.1	Procedures shall be in place at storage and production areas to prevent cross contamination and misuse of raw materials, packaging and finished products.		The manufacturer had established procedure to prevent the contamination of raw materials, packaging and finished products, and per manufacturer tour, most sampled materials and products were properly stored, but a few part of packing materials were directly placed onto floor in packing area, which may lead to the material contamination.
4.3.3	Materials and products are used following a FIFO policy or based on its shelf life.	Minor (YELLOW)	The manufacturer had established warehouse management instruction to state the FIFO requirement, and per manufacturer tour, most incoming materials and products were properly identified with incoming date, production date or expiry date to ensure the FIFO & shelf life, however, it was found that a few part of surplus fabric materials in incoming materials warehouse was not identified with incoming date to ensure FIFO.
4.5.1	The company shall establish procedures for the identification, segregation, investigation and disposition of non-conforming raw materials (including packaging), work-in-progress and finished products. Disposition of finished products shall be per any applicable customer requirements.	(YELLOW)	The manufacturer established non-conforming materials handling procedure, most non-conforming materials/products were properly identified and segregated, but a few part of non-conforming semi-finished products were not identified with reject reason, quantity, date, etc. in the reject area of sewing workshop.

The above reflects our findings for the particular factory in concern on the date of our service only. This report does not certify, confirm or imply: a) compliance with any government, industry or association regulations or standards, unless stated otherwise; or, b) the quality of any specific products manufactured by the factory/sellers/suppliers; or, c the shipment of any specific products. This report does not discharge or release the factory/sellers/suppliers from their commercial, legal or contractual obligations with buyers in respect of products manufactured by the factory/sellers/suppliers. Our services, including reports and certificates, are subject to the General Conditions of Service of Bureau Veritas which have been sent to your company. They can be resent upon written request. This report cannot be partially copied. Any reader other that the party for which this report has been specifically issued is hereby informed that the General Conditions of Service of Bureau Veritas contain liability limitation provisions. BV Office Name: Bureau Veritas Shenzhen Company Limited Address:3F, Block A, Min Li Da Industrial Bldg.,4th Area, Hong Hua Ling Industrial Area, Xili, Nanshan District, Shenzhen City, Guangdong Province. Country Name: China

7	PERSONNEL		
7.1.1	Procedure shall be in place and implemented to ensure that all personnel, including temporary personnel and contractors, shall be appropriately trained prior to commencing work and when any procedure or process changes occur.	(ORANGE)	The manufacturer established training procedure, training plan, most workers were suitably trained, relevant records were kept, but no training record was available for one new employee in packing workshop.
7.1.3	The inspectors shall be trained in the use of the inspection schedule, sampling plan and inspection criteria for the components and semi-finished product being assessed.		The factory conducted training to all inspectors in the use of the inspection schedule, sampling plan and inspection criteria, relevant records were kept, but based on interview, one of the IQC inspectors was not familiar with the sampling plan and inspection criteria she used.
8	Process Management		
8.2.3	The safety or legality of products are not jeopardised during maintenance operations.	Minor (YELLOW)	The manufacturer did not establish procedures to ensure the safety or legality of products were not jeopardised during maintenance operations, for reference, no maintenance operations were observed on site during manufacturer tour, based on the interview, the employee stated that materials and products would be removed when maintenance operations were performed.
8.2.4	Procedures shall be in place for process / equipment changeover.	Minor (YELLOW)	The manufacturer established procedure for process/equipment changeover, based on interview, the employees knew the requirements, but not all of the records were kept.
8.3.2.2	A duplicate of an approved production sample with comments shall be provided and in use for all necessary operations as reference for operators.		The manufacturer provided approved samples in most working areas, but one of the samples was not signed in sewing workshop.
9	Toys Specific		
9.6.7	Cut panel replacement procedures shall be in place to replace defective panels with fabric from the same dye lot or shade.		The manufacturer established cut panel replacement procedures, relevant records were kept, but the records were not fully filled, no fabric lot number was filled in the record.
9.19.2	Defective and overrun products shall be handled as per defined instruction.	Minor (YELLOW)	The manufacturer established procedure to handle the defective and overrun products, but no relevant handling records were kept.

Report No.: 10193470987 Factory name: Jia Ying (Hui Zhou) Umbrella Co., Ltd Audit date: July 13-14, 2020 Page 1 of 7

Digital Photo Records

		TRUE MAY MAY MAY MAY MAY MAY MAY MAY MAY MAY
1) Factory entrance	2) Factory name at entrance	 Similar products produced for the client
 Incoming materials warehouse 	5) Finished products storage area	6) Chemical materials storage area
a a cara a ca a cara a car		
7) MSDS posted	8) Cutting area	9) Sewing area
10. Accomply creat/band	11) Decling area	12) IOC impression even
10) Assembly area(hand stitching)	11) Packing area	12) IQC inspection area

	作 点 - 2000 型 验 布 机	<section-header><section-header><section-header><section-header><section-header><section-header></section-header></section-header></section-header></section-header></section-header></section-header>
13) IQC inspection instruction on site	14) Fabric inspection machine	15) Inspection instruction for fabric inspection
161 Buppabar and weight	12) IBOC inequation area	<section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><list-item><list-item><section-header><section-header><section-header><section-header><section-header><list-item><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></list-item></section-header></section-header></section-header></section-header></section-header></list-item></list-item></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header>
16) Puncher and weight	17) IPQC inspection area	18) Inspection instruction on site
	<page-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><text><text><text></text></text></text></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></page-header>	
19) Final inspection and testing area	20) Final inspection instruction on site	21) Pull tester
ENERGY TER		<section-header><text><text><text><text><text></text></text></text></text></text></section-header>
22) Color fastness tester	23) Temperature tester	24) Testing instruction on site



Report No.: 10193470987 Factory name: Jia Ying (Hui Zhou) Umbrella Co., Ltd Audit date: July 13-14, 2020 Page 4 of 7



Report No.: 10193470987 Factory name: Jia Ying (Hui Zhou) Umbrella Co., Ltd Audit date: July 13-14, 2020 Page 5 of 7



	Res of the second	Nil
61) NC-4.5.1 A few part of non-conforming semi-finished products were not identified with reject reason, quantity, date, etc. in the reject area of sewing workshop.	62) NC-8.3.2.2 One sample was not signed in sewing workshop	63)

Report No.: 10193470987 Factory name: Jia Ying (Hui Zhou) Umbrella Co., Ltd Audit date: July 13-14, 2020 Page 7 of 7

Business license





CODE OF CONDUCT (page 1)

Bureau Veritas Consumer Products Services Pvt Ltd, 7F Octa Tower, 8 Lam Chak Street, Kowloon Bay, Kowloon, Hong Kong.

INSPECTION, AUDIT & ASSESSMENT

Tel: +852 2418 1222 www.cps.bureauveritas.com

Factory Integrity Acknowledgment

Inspection / Audit No.:	
Factory / Supplier:	
Inspection / Audit Date:	

Dear Supplier

Bureau Veritas, Consumer Products Services Division provides independent, impartial and objective assessment and inspection services for our global clientele. Our assessment and/or inspection findings will be duly recorded and reported to our clients. We request your cooperation to enable us to effectively execute this process.

We operate a strict Code of Ethics, which prohibits the direct or indirect acceptance of gifts, payment or benefit in any form. This Code of Conduct letter is presented to the management of your facility for the purpose of setting out acceptable conduct whilst our representatives perform their job at your facility. We ask that you read this document and sign it to confirm your understanding and agreement.

- Never, under any circumstances, give in to demands or requests for benefits or payments from a BV representative. If a BV representative asks for any direct or indirect benefit, you must contact the BV office or the contact details below. You must also contact BV immediately for any other issues or concerns on the BV representative/s assigned for the service.
- 2. Never, under any circumstances, collude or offer a facilitation payment, bribe, gift or any other benefit to a BV representative. Any benefit given to a BV representative will be construed as a corrupt practice and will be reported to our client. This includes "tea money", "hardship appreciation", or any other benefits regardless of the actual value.
- 3. BV is committed to fully complying with local laws and regulations, including such on anti-corruption and bribery. Where appropriate, BV will not hesitate to alert or cooperate with law enforcement authorities on suspected or actual offenses
- 4. Do not put any undue pressure on our representatives to execute their work if conditions stipulated by the client are not met. Also, do not put any undue pressure on our representatives to amend the results or recording of their findings.
- 5. During the work execution, our representatives may be required to take photos of the factory facilities, products being inspected or assessment/inspection processes in order to validate findings. Please ensure this process is not obstructed Documents, pictures, or any other information gathered during the course of the BV service will be kept confidential.
- 6. Provide a safe environment that allows BV representatives to do their job properly. This may mean assistance with locating moving and opening cartons for inspections and arranging a private and suitable place for audits. It also means pointing out any safety hazards, and providing appropriate personal protective equipment and necessary training regarding any risk that may be encountered. BV representatives will check the working environment in accordance with BV's safety requirements in the "2 Minutes for my safety assessment form". In case potential risks are identified, which may jeopardize auditors' and inspectors' health or safety, they have the right to discontinue the services if you cannot eliminate such risks.
- We require factory to assign only authorized personnel to be present in the inspection / audit room to coordinate during BV services, so that there is no overcrowding. After completion of the service, the findings will be discussed only once and therefore factory should arrange their authorized personnel to be present during the closing meeting.
- 8. We require only authorized factory representative to sign the report prepared by our representatives to acknowledge the execution of their work and findings
- 9. In some cases we are asked by client to submit hand written reports and digital images from the factory and would request that our representatives use your facilities. With regards to inspections, our representatives will request to take shipment samples for verification.
- Trainee(s) may accompany senior inspectors /auditors on the visit to your factory. If needed, an interpreter may also
 accompany the BV representative. Their presence will neither result in additional charges to you, nor affect the final results.
- 11. To enforce our integrity policy, we may send mystery inspectors/auditors to perform services or other BV representatives to perform surprise checks and report to our client any breach of the policy.

"BUREAU VERITAS PROPRIETARY- unpublished work, copyright [2013] Bureau Veritas - DO NOT DISCLOSE OUTSIDE YOUR ORGANISATION WITHOUT SUPPORT MULTICAL PURPORT AND A CONSENT ORGANISATION WITHOUT SUPPORT AND A CONSENT SD002_CODE_OF_CONDUCT_LETTER(EN)_GLOBAL_VERSION 03_23MAR2020

Page 1 of 2



CODE OF CONDUCT <u>(page</u> 2)

7F Octa Tower, 8 Lam Chak Street, Kowloon Bay, Kowloon, Hong Kong.

INSPECTION, AUDIT & ASSESSMENT Factory Integrity Acknowledgment

Bureau Veritas Consumer Products

Tel: +852 2418 1222 www.cps.bureauveritas.com

PART 1: Factory declaration (To be filled by the factory once BV COC is explained by the BV staff).

We confirm that we received the BV Code of Conduct and that the contents were explained by the BV representative, Mr. / Ms. ______on _____on _____at ____HHMM___ and we understand the contents, spirit and intent of the BV procedure on Integrity. The following BV representatives performed the service:

Signature of Factory Representative

Factory Representative's contact number

PART 2: Factory declaration (To be filled by the factory after completion of the service. In case there is anything to declare confidentially, specific details can be sent directly to ethics@hk.bureauveritas.com).

ltem	Please declare if benefits were offered to the BV staff \checkmark	Yes	No	Item	Please declare if benefits were offered to the BV staff ✓	Yes	No
Α	Meals			в	Transportation		
С	Accommodation			D	Money		
Е	Gifts			F	Other Benefits/Favors		
Expl G	ain details of free or subsidized benefits offered Please declare about use/role of consultants	Yes	No		n details of the consultant		
	you contacted by a consultant for this ction/audit?			If yes,	please specify when, who and why		
	you used a consultant's services for this ction/audit?			If yes,	please specify when, who and why		

We acknowledge that the above information is true and accurate. We understand that BV could and will report to program clients and/or law enforcement authorities any suspected improprieties or illegal activities.

We also acknowledge that the BV representative/s explained the findings of the service and we agree with it.

Signature of Factory Representative

Name and Designation

Date and Time

Please contact the following to make any complaints or suggestions: Complaints mailbox: Ethics@hk.bureauveritas.com Company Chop Tel: +1 716 505 3582 Jamey Appler Vice President & CPS General Counsel, Email: jamey.appler@us.bureauveritas.com Risk and Compliance Officer

"BUREAU VERITAS PROPRIETARY- unpublished work, copyright [2013] Bureau Veritas - DO NOT DISCLOSE OUTSIDE YOUR ORGANISATION WITHOUT BUREAU VERITAS PRIOR WRITTEN CONSENT". SD002_CODE_OF_CONDUCT_LETTER(EN)_GLOBAL_VERSION 03_23MAR2020 Pag Page 2 of 2

	<u>行为守则(第1页)</u> INSPECTION, AUDIT & ASSESSMENT	Bureau Veritas Consumer Products Services Pvt Ltd, 7F Octa Tower, 8 Lam Chak Street, Kowloon Bay, Kowloon, Hong Kong	
	工厂廉政确认书	Tel: +852 2418 1222 www.cps.bureauveritas.com	
	检验/审核号码:	1-12-112-087	
	厂商:	10193470987 Tig. Vog (Huizhon) //mbrella	to It
	检验/审核日期:	Jia Ying (Huizhon) Umbrella	209-
		Jug 12 8 19, 2010	
敬的厂商,			
中向客户汇报评估及检验过 W实施一套严格的道德行	务事业部(以下简称 BV)致力于为海内外客户提供独立、 程中的各种发现。为确保整个工作过程的有效进行,请您 为规范,禁止员工直接或间接接受任何形式的礼物、报酬; 工作期间的行为规范。请阅读此文件并签名、盖章以确认	给予最好的合作。 或好处。本行为守则呈递给贵公司管理层以	
TINGT A DU TURALI	工作物间的行为规范。有网族此天计开金石、量卓以明认	9. 赵武 [19] 叶叶 丹明 赵弘 。	
	代表素要任何直接或间接形式的报酬或好处时,均不予理	会并按以下联络方式直接联系 BV 办公室。	
如有其他与执行工作的	BV 代表相关的问题或关注,也请立即联系 BV 公司。		
2. 任何情形下,不串通不 户汇报厂商给予 BV 代	斯略 BV 的代表,不提供任何报酬、礼物或其他形式的短表任何好处的行为,包括茶水费、辛苦费、感谢费或其他	子处给 BV 的代表。BV 将按行贿处理并向客 形式的好处,无论实际价值多少。	
 BV 一贯遵守当地的法 汇报给当地执法部门回 	律法规,包括遵守相关反腐败及反商业贿赂方面的法律法规 发与其合作进行调查。	规。对于可疑的或实际的违法行为,BV将	
当的影响或者压力去i	的检验和/或评估条件时,不对 BV 代表施加任何不合适的影式图修改任何报告结果或记录。		
行拍照。请确保不阻	的工作发现, BV 代表在执行工作时将根据需要对工厂的设 得拍照过程的正常进行。BV 将对执行工作过程中收集的文	H, M/IX/ CIRCLE OF	
作:对于工厂评估, 对可能遇到的危险提 途。如果发现有任何	作环境使 BV 代表得以顺利地工作。例如,产品检验时,请 提供合适安全的工作场所进行员工面谈工作,同时告知危险 供必要的培训。按照 BV 的安全要求"2分钟的安全检查表 可能对检验员和审核员安全和健康造成的隐患,且工厂无法	", BV 代表将检查检验和评估的工作环 告排除这些隐患时, BV 代表有权中止服务。	
	授权代表在检验\审核地点配合 BV 工作,以免造成拥挤。 参加末次会议。		
	请厂方授权代表在报告上签字以确认知晓 BV 代表的工作的要直接从工厂将手写报告和数码照片传出,请给予此方面的	的进行情况和结果发现等。某些情况下,应]协助。	
	PV 伊妻 今要求取走一些出货样品以便日后参考。		
9. 产品检验工作元成石	1职员跟随资深职员到工厂访问。根据需要,翻译人员也会限	8同到访。但这种安排既不会产生额外的人	
10. 我们 会安排见习	· 不同 \$10 月11 日前 \$26 \$15 \$26 \$	·····································	
10. 我们自己会安排见习 工费的也不会影响	如此可能会派出的政治和"	BV代表来检查工作,加有工产	
10. 我们自会安排见之 工费也不会影响 11. 为贯为 V 廉政政策 行为 被呈报给名	,我们可能会派出特殊检验/评估人员来执行工作或派其他	BV代表来检查工作,用有工作量的	
工数で低小去の中	,我们可能会派出特殊检验/评估人员来执行工作或派其他	BV代表来检查工作,所有工作量的	
11. 为贾义 W 廉政政策 行为 11. 为贾义 W 廉政政策	,我们可能会派出特殊检验/评估人员来执行工作或派其他		

