

IPX7 TEST REPORT

Report Reference No. : NBZT032501200901

Applicant Company : Grin (Hangzhou) Technology Co., Ltd.

Address..... : Building Yongsheng, Xiaoshan Economic And Technological
Development Zone, Xiaoshan District, Hangzhou, Zhejiang

Manufacturer Company..... : BeBeauty (Hangzhou) Technology Co., Ltd.

Address..... : Building 1, NO.768 Jianghong Rd, Binjiang District, Hangzhou
Zhejiang

Sample Name : Electric Toothbrush



Model Number : V4R, V2, V2R, V3, V4, V5, V5R, V6, V6R, V8R, K8, K12, K20

Date of Report : Jan. 16, 2026

Date of Tested : Jan. 12, 2026

TESTING LABORATORY..... : Ningbo Drotek Testing Technology Service Co., Ltd.

ADDRESS : North Half, 2/F., Office Building, & Buliding18, No.518, Xinmei
Road, High-tech Zone, Ningbo, Zhejiang, China (Phase II,
Industrial Park of Ningbo AUX Industrial Management Co., Ltd.)

	Name	signature	Date
Testing Engineer	Tony Hu		2026.01.16
Approving Manager	Gorden Zhu		2026.01.16

Notes:

1. This report will be invalid if duplicated or photocopied in part.
2. This report refers only to the specimen(s) submitted to test, and is invalid as separately used.
3. This report is invalid without examination stamp and signature of this company.
4. The tested specimen(s) will be preserved for ninety days from the date issued, if not taken back by the applicant.

1: Test item

IPX7 test

2: Test environment

Temperature: 21.2°C

Relative humidity: 58.9%RH

3: Test sample description

The test sample comes from the customer. It was an electric toothbrush.

The models V2, V2R, V3, V4, V5, V5R, V6, V6R, V8R, K8, K12, K20 were the same as V4R, except for the model's name.

The IPX7 test was selected as a representative to perform on model V4R.

4: Testing standard

IEC 60529:1989+A1:1999+A2:2013 Degrees of Protection provided by enclosures (IP code).

5: Test requirement and result

IPX7 test

Test requirement: In general, after complete tests, specimen operates normally and no feed water, or if have water, should not affect the normal operation of the equipment or safety.

Test result: There is no water inside, not affect the creepage distance and normally operation, the test is pass.

Attachment: Photos of the appliance

Photo 1

Description: Overview of V4R



Photo 2

Description: Overview of V4R



Photo 3

Description: Overview of V4R



Photo 4

Description: Overview of V4R



Photo 5

Description: After testing of V4R



Description: After testing of V4R



-- The End of Report--