



Cherry Mai  
 World of Lights Lighting Factory  
 No.18 Lefeng 8th Road  
 Sansha Industrial Park  
 Henglan Town  
 Zhongshan  
 Guangdong 528478 CHINA

Date: 2016/03/30  
 Subscriber: None  
 PartySite: 1536227  
 File No: E480725  
 Project No: 4787370101  
 PD No: 16M15090  
 Type: L  
 PO Number:

Subject: **Procedure And/Or Report Material**

The following material resulting from the investigation under the above numbers is enclosed.

**Issue**

<u>Date</u>	<u>Vol</u>	<u>Sec</u>	<u>Pages</u>	<u>Revised Date</u>
2015/12/23	1	1	Revised Description Page(s) 1, 2, 5, 6	2016/03/29

Inspections at your plant will be conducted under the supervision of LI JIAN, UL INSPECTION CENTER GUANGZHOU, CHINA NAT'L IMPORT & EXP COM INSPCTN CORP, 66 HUA CHENG DA DAO, WEST TOWER, 17TH FL, ZHU JIANG XIN CHENG, GUANGZHOU, GUANGDONG, China, 510623., PHONE: 20-38872860, FAX: 20-3829-0799, EMAIL: ulic316@ccicgd.com

Please file revised pages and illustrations in place of material of like identity. New material should be filed in its proper numerical order.

NOTE: Follow-Up Service Procedure revisions DO NOT include Cover Pages, Test Records and Conclusion Pages. Report revisions DO NOT include Authorization Pages, Indices, Section General Pages and Appendixes.

Please review this material and report any inaccuracies to UL's Customer Service Professionals. Contact information for all of UL's global offices can be found at <http://ul.com/aboutul/locations>.

If you'd like to receive updated materials FASTER, UL offers electronic access and/or delivery of this material. For more details, contact UL's Customer Service Professionals as shown above.

This material is provided on behalf of UL LLC(UL) or any authorized licensee of UL.

NWT File

UL INSPECTION CENTER 316